

bosal

Инструкция по монтажу тягово-сцепного устройства шарового типа 5255 А для автомобилей **Chevrolet Rezzo** **Daewoo Tacuma**

Chevrolet Rezzo	2004/4- 2008
Daewoo Tacuma	2000-2004/4
	1100
	50
	21,4





462800,

« - »
18
: (35363) 7-05-06
/ : (35363) 7-13-20
(495) 785-66-07
www.bosal-autoflex.ru


« - »;	(8182) 22-48-15
" " 8(8442) 98-74-98	" 8(343) 379-39-89, 373-42-73
" " " 8(343) 26-88-308	" " 8(3952) 710-194
" " " 8(495) 777-54-59	" " 8(495) 745-79-11
" " " 8(495) 788-95-97	" " 8(495) 720-51-03
" " " 8(495) 720-51-03	" " 8(3532) 57-99-85
" " " 8-905-899-5012	" " 8(383) 291-59-60
" " " 8(831) 279-53-24	" " 8(3422) 98-27-20
" " " 8(342) 220-87-87	" " 8-927-002-90-06
" " " 8(3462) 24-00-44	" " 8(3842) 21-14-76
" " " 8-902-940-4151	" " 8(3452) 32-22-12, 41-52-62
" " " 8-961-213-0278	" " 8-917-347-1700
" " " 8(351) 269-44-75, 900-72-73	" " 8(3512) 773-76-91

41.55-2005.

()
 () ()
 &12 .. () &16
 () &12
 &16 ()
 () &12
 10=4,7
 12=8,1 , / 12=9,5



	1
	1
	1
	1
	1
	1



12 35	2
12 1,25 75	2
10 120	6
12 50	2
12 /	3
12 1,25 /	2
10 /	6
12	1
12	7
12	4
10	6
L=80	6
E25 13 L=12	1
	3
	1
190	1
VH 0858 ()	1
	2
	1
	1
	1
	1